



Release Notes

Lifesize Icon Release v2.0.5

What's New.....	1
Known Issues	1
Interoperability	2

For more information about your Icon system, [click here](#).

What's New

- Support for the automation command line interface is available in this release. Access the documentation from your Icon software package (https://<icon_ip_address>/docs/clish) for more information about using the CLI.
- Disabling SSH no longer results in the phone being unable to start or displaying the message “The phone is connected to an unsupported system.” (PKS-7215)

Known Issues

Following are known issues and their workarounds, if available. Numbers in parentheses are for internal tracking.

- Adding a call from Internet Explorer v11 may result in a delayed response. **Workaround:** Use another supported browser. (PKS-7084)
- Disabling CEC may fail. (PKS-7027)
- Some secondary displays may be unable to go to sleep mode. (PKS-6190)
- Changing **Video Call Output** in the web interface fails if a call is in progress. The setting for **Voice Call Output** controls the active speaker for both video calls and voice calls. **Workaround:** Change the value prior to a call starting or use the value set for **Voice Call Output** for video also. (PKS-7156)
- Incorrect video resolution may occur for some displays with Icon 800. **Workaround:** Unplug the HDMI cable and plug it back. (PKS-7108)
- Values for **Remote IP** and **Protocol** fields in the CDR logs for recording may be incorrect. (PKS-5389)
- Presentations are not supported in SIP calls that use UDP and are placed through Lifesize UVC ClearSea. **Workaround:** Use TCP for SIP calls that are placed through Lifesize UVC ClearSea. (PKS-5687)
- HDMI audio might not function appropriately after a Lifesize Icon restarts or awakens. **Workaround:** Unplug the HDMI cable from the Icon and plug it back in. (PKS-5646)
- Input selectors from the web interface for Icon 800 are not available. **Workaround:** Select inputs from the main UI. (PKS-7173)

- Locking the camera position from the web interface for Icon 800 may not take effect. (PKS-7172)
- Refreshing the license page from the main screen may not correctly update values in the web interface.
Workaround: Click **Refresh** on the web interface to show the latest data. (PKS-7117)
- Lifesize Icon 800 only recognizes Lifesize Cameras as the primary input. If you are using a Visca camera as the primary input (DVI 1), the system is unable to recognize it. (PKS-7343)
- Switching between video inputs in configurations with two DVI inputs connected on Icon 800 results in unpredictable video behavior. **Workaround:** Reboot the system to correct the problem. (PKS-7134)

Interoperability

This release supports the following products.

Browser support	Windows 7 Internet Explorer 11, 10 Firefox 29, 28, 27 Chrome 34, 33, 32 Mac OSX 10.9 (Mavericks) Chrome 34, 33, 32 Firefox 29, 28, 27 Safari 7.0.3
USB serial port adapters	AirLink101 AC-USBS Belkin Codi Keyspan USA-19HS
Cisco/Tandberg	Cisco SX20: V8.2 Tandberg C Series: TC 4.2.3
Polycom	HDX Series: 3.0.4 Group 300: 4.0.2 Group 500: 4.0.2
Radvision	XT5000: 03.00.00115 V3_0_115B